

CITY OF MILL CREEK SURFACE  
WATER REHABILITATION  
PROGRAM: CCTV RECORDINGS  
BY YEAR WITH FAULT  
LOCATIONS

LEGEND

FAILED PIPE, HIGH PRIORITY REPAIR

PIPE REPAIR REQUIRED WITHIN 10 YEARS

SINK HOLE REPAIR IN PROGRESS

2012 CCTV PROGRAM

2014 CCTY PROGRAM

2015 CCTV PROGRAM

2016 CCTV PROGRAM

2017 CCTV PROGRAM

2018 CCTV PROGRAM  
18" OR GREATER PIPE PROGRAMMED TO BE CCTV

FAULTS FOUND IN 12" PIPES. NO FAULTS  
FOUND IN PIPES 18" OR LARGER.

08/14/2018

